



Quick Stop Maneuver with Lifesling: Good short-handed solution.



"Figure of 8" MOB Maneuver: Image from U.S. Navy





Following these rules can prevent virtually all man-overboard incidents:

- 1. Remain sober, especially if you expect to go on deck for any reason.
- 2. Wear non-skid footwear when working on deck and have non-skid paint or pads in critical work areas.
- 3. Walk or crawl on the uphill windward side in a crouched position with a low centre of gravity and wide-based stance when the boat is rolling, heeling, or pitching.
- 4. If the boat's motion is too violent to allow a person to stand, then crawl or slide along the deck.
- 5. Use a safety harness (with two shackles) as a "third hand," secured to a strong attachment point, with a quick release shackle at the body end of the harness.
- 6. Use a safety harness whenever going aloft in the rigging or climbing any superstructure.
- 7. Avoid leaning overboard with all your weight on a lifeline or stanchion.
- 8. Know the location of secure handholds and grab rails so you can find them at night.
- 9. Know the safe routes to avoid tripping on deck hardware, vents, and hatches, especially at night.
- 10. Do not urinate from the afterdeck in rough weather unless you are kneeling and attached with a safety harness.
- 11. Wear a safety harness whenever seasick; vomit into a bucket rather than leaning overboard.
- 12. In heavy weather, sleep in the harness and be ready to attach the tether to a cockpit pad-eye before coming on deck.



SEARCH PATTERN

